Ecusta Trail - Issue Tracking Dashboard

Select an Issue Type
No issue type selected

Select Resolved Status
All statuses

Select a date
2/1/2026 - 3/4/2026

Issue Reports - Resolution Status

🔍 Search...

Date Reported: 3/2/26, 8:21 AM

Issue Type: Trail Surface Problem (Broken pavement, wash out, etc.)

Issue Resolved: no

Report Comments: Reflective lettering needs repaired by const. company - Mike

Staff Comments:

Date Reported: 2/27/26, 9:00 AM

Issue Type: Tree/Vegetation

Issue Resolved: no

Report Comments: Widow maker tree limb, needs professional- Mike

Staff Comments:

Date Reported: 2/25/26, 1:01 PM

Issue Type: Trail Surface Problem (Broken pavement, wash out, etc.)

Issue Resolved: no

Issues Resported

12

Resolved
3

In Progress
3

Unresolved
6

Issue Reports - Full Details

◀ 1 of 12 ▶

Reported Issues

Date	3/2/26, 8:21 AM
Closest Mile Marker	Turley Falls
Issue Type	Trail Surface Problem (Broken pavement, wash out, etc.)
Comments	Reflective lettering needs repaired by const. company - Mike
Henderson County Residency Status	yes
Issue Resolved	no
Date Issue Resolved	
Response Comments	

Photo of Issue

Issue Report by Type

Vehicle on Trail 2
Other 3
Grafitti/Vandalism 1
Tree/Vegetation 1
Road Crossing Issue 3
Trail Surface Problem (Broken pavement, wash out, etc.) 2

Issue Locations

State of North Carolina DOT | Esri | TomTom | Garmin | SafeGraph | GeoTechnologies, Inc | NASA | NGA | USGS | METI/NA... Powered by Esri

Issue Reports by Date

Legend:
- Grafitti/Vandalism
- Vehicle on Trail
- Tree/Vegetation
- Trail Surface Problem (Broken pavement, wash out, etc.)
- Road Crossing Issue
- Other

X-axis: Month Issue Reported (Feb, Mar)
Y-axis: # Issues Reported