

Addendum #1 TEDC Building Window Seals and metal Panel Splines

Adding Alternate #1

Alternate #1 Event Hall Inspection: Visually inspect all rubber splines on the extruded metal panels of the TEDC Event Hall. Note any additional rubber spline repairs needed on the TEDC Event Hall that were not visible from the ground during the Pre-Bid site visit.